

Contact: Carl Davis
 200 Jetport Rd.
 Brandon, MS 39047
 Phone: 601-936-0777



Spey MK 511-8 - S/N 11032

TTSN	5,734.3	TSO	3,294.3
TCSN	4,635	CSO	2,718

PART NAME	PART #	SERIAL #	MOD STD	TOTAL HRS	TOTAL CYC	CYC LIMIT	CYC REMAIN
LP COMP SHAFT	EU35742A	TF201	2982	5,734.3	4,635	20,000	15,365
LP COMP EXT SHAFT	EU62068A	SJ306	2982	5,734.3	4,635	20,000	15,365
HP COMP DISC STG 1	JR17214	840CCA	5283	5,734.3	4,635	13,000	8,365
HP COMP DISC STG 2	JR18742	647CAD	5283	15,304.3	11,029	20,000	8,971
HP COMP DISC STG 3	JR18743	SETP11206	5283	3,294.3	2,718	20,000	17,282
HP COMP DISC STG 4	JR18744	DETP1364	5283	11,306.3	8,320	20,000	11,680
HP COMP DISC STG 5	JR18746	989CAP	5283	13,831.3	9,827	20,000	10,173
HP COMP DISC STG 6	JR18748	516CAH	5283	17,148.3	11,597	20,000	8,403
HP COMP DISC STG 7	JR13814	467CAK	5283	15,304.3	11,330	20,000	8,670
HP COMP DISC STG 8	JR13815	782EAM	5283	5,734.3	4,635	20,000	15,365
HP COMP DISC STG 9	JR13816	245EAN	5283	5,734.3	4,635	20,000	15,365
HP COMP DISC STG 10	JR18750	15EAN	5283	5,734.3	4,635	20,000	15,365
HP COMP DISC STG 11	JR18751	678EAM	5283	5,734.3	4,635	20,000	15,365
HP COMP DISC STG 12	JR13820	SETM13632	5283	3,294.3	2,718	13,000	10,282
HP COMP DISC SEAL STG 12	EU57312	325YH	2651	5,734.3	4,635	13,000	8,365
HP TURB DISC STG 1	JR24280	540GAE	5824	5,734.3	4,635	17,500	12,865.
HP TURB DISC STG 2	JR11312A	448GAE	4412	5,734.3	4,635	17,500	12,865
LP TURB DISC STG 1	EU75913A	462BM/A	3892	5,734.3	4,635	20,000	15,365
LP TURB DISC STG 2	EU59228	812BM	5155	5,734.3	4,635	20,000	15,365
LP COMP DRIVE SHAFT	JR17862	17NWB	5097	5,734.3	4,635	20,000	15,365
LP TURB SHAFT	EU60808A	PABX20513A	5155	3,294.3	2,718	20,000	17,282
HP TURB SHAFT	JR23587	775WL	5675	5,734.3	4,635	20,000	15,365
HP COMP REAR SHAFT	EU57333A	843ND	2651	20,040.3	11,108	20,000	8,892
HP TURB STG 2 LOC SLEEVE	JR31062	DQDM2164		1,371.4	1,195	22,000	20,805

ADDITIONAL INFO:

- Last OH – Rolls Royce on 10 Oct 2001
- Last 10 Yr Calendar Inspection - Dallas Airmotive on 09 Mar 2011
- Non-incident
- Performance Run prior to removal completed, results available on request

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.