



Contact: Carl Davis
200 Jetport Rd.
Brandon, MS 39047
Phone: 601-936-0777

PT6A-135
PCE-92225

TTSN	10,690.4
TCSN	12,983
TSO	3375.5
CSO	4274
TSHSI	0.00

PART #	SERIAL #	DESCRIPTION	CSN	CYC LIMIT	CYC REM
3013111	1F439	Hub Assembly	12,983	19,000	6,017
3013712	8E835	Compressor Disc 2nd Stage	12,983	28,000	15,017
3011713	8E552	Compressor Disc 3rd Stage	12,983	25,000	12,017
3013176	1B521	Impeller	12,983	19,000	6,017
3014211	3E875	Compressor Turbine Disc	12,983	16,000	3,017
3022312	2F124	1 st Stage PT Disc	12,983	30,000	17,017

ADDITIONAL INFO:

- Last Overhaul by DALLAS AIRMOTIVES 03 Nov 2009
- Fresh HSI in Jan 2021
- Logbooks available dated back to birth

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.