



# DAVIS

## AVIATION, INC.

www.davisaviation.com

---

Contact: Carl Davis  
200 Jetport Rd.  
Brandon, MS 39047  
Phone: 601-936-0777

---

## PT6A-42

### PCE-94615

<b>TTSN</b>	4,809.3
<b>TCSN</b>	4,208
<b>TSO</b>	0
<b>CSO</b>	0
<b>TSHSI</b>	N/A

<b>PART #</b>	<b>SERIAL #</b>	<b>DESCRIPTION</b>	<b>CSN</b>	<b>CYC LIMIT</b>	<b>CYC REM</b>
3035801	57A743	Rotor Compressor	4,208	20,000	15,792
3023112	A0033YE7	Compressor Disc 2nd Stage	0	20,000	20,000
3023113	A003ANAR	Compressor Disc 3rd Stage	0	20,000	20,000
3035635	4B891	Impeller	4,208	20,000	15,792
3049291-01	YUAA013A372	Compressor Turbine Disc	0	10,000	10,000
3029312	66A271	1 <sup>st</sup> Stage PT Disc	4,208	30,000	25,792
3029313	63A498	2 <sup>nd</sup> Stage PT Disc	4,208	30,000	25,792

### **ADDITIONAL INFO:**

- Overhauled by Dallas Airmotive October 2013
- Standard Aero Repair January 2017 (for improper preservation)
- Logbooks back to birth excluding 2003-2009 (less than 400 cycles)

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.