



# DAVIS AVIATION, INC.

Giving Wings to Truth  
www.davisaviation.com

---

Contact: Carl Davis  
200 Jetport Rd.  
Brandon, MS 39047  
Phone: 601-936-0777

---

## JT15D-5A PCE-108049

<b>TTSN</b>	4,659.0
<b>TCSN</b>	5,694
<b>TSO</b>	1,214.0
<b>CSO</b>	1,484
<b>TSHSI</b>	1,214.0

<b>PART #</b>	<b>SERIAL</b>	<b>DESCRIPTION</b>	<b>TSN</b>	<b>CSN</b>	<b>HRS REM</b>	<b>CYC REM</b>
3037911	7Y063	L COMP HUB 1	4,659.0	5,694	10,341.0	6,306
3034112	8Y865	L COMP HUB 2	4,659.0	5,694	10,341.0	8,306
3033682	5D728	IMPELLER	4,659.0	5,694	10,341.0	3,306
3036411	11A368	HPT	4,659.0	5,694	10,341.0	8,306
3022212	7Y767	LPT STG 1	4,659.0	5,694	10,341.0	8,306
3036113	13A872	LPT STG 2	4,659.0	5,694	10,341.0	8,306
3029601	N/A	HPT BLADES (6 NEW 3055021-01 @ OVH)	N/A	N/A	N/A	N/A

### **ADDITIONAL INFO:**

- Non-incident
- LAST OVH – ATLANTIC TURBINES OCTOBER 13, 2004
- LAST HSI – ATLANTIC TURBINES OCTOBER 13, 2004

Disclaimer: Verification of the above provided information shall be the sole responsibility of the buyer/installer. Davis Aviation, Inc. is not responsible and accepts no liability for the use of this information, or for any consequences of any actions taken, or any loss or damage caused, or alleged to have been caused directly, or indirectly on the basis of the information provided above.