

Contact: Carl Davis 200 Jetport Rd. Brandon, MS 39047 Phone: 601-936-0777

PT6A-25A PCE-48158

| TTSN | 3,651.0 | | |
|-------|---------|--|--|
| TCSN | 2,449 | | |
| TSO | 0 | | |
| CSO | 0 | | |
| TSHSI | 0 | | |

| PART# | DESCRIPTION | CSN | CYC LIMIT | CYC REM |
|---------|---------------------------|-------|-----------|---------|
| 3013111 | Rotor Compressor | 2,449 | 19,000 | 16,551 |
| 3013712 | Compressor Disc 2nd Stage | 2,449 | 24,000 | 21,551 |
| 3011713 | Compressor Disc 3rd Stage | 2,449 | 25,000 | 22,551 |
| 3013176 | Impeller | 2,449 | 19,000 | 16,551 |
| 3013411 | Compressor Turbine Disc | 2,449 | 16,000 | 13,551 |
| 3022412 | 1st Stage PT Disc | 2,449 | 20,000 | 17,551 |

- Fresh overhaul TSO: 0
- Non-incident
- Full Logbooks